

Tuesday March 22, 2011
DonRut

10³⁰ - 12³⁰

p 23+

p 25 - Freedom Quad Pond - reduced discharge during storms - to about 10% of present - 100 year storm 144.51 CFS to 10.48 CFS after rebuilding of Freedom Quad Pond.

p 29 o sediment fence

- o 12" of clay liner in forebay & extended detention basin
- o 60" pipe
- o 54" pipe
- o 18" pipe
- o 42" pipe
- o 15" pipe

p 22 "The existing Freedom Quad basin was not designed with adequate capacity to contain the 10 year storm from just the Freedom Apartments without an increase in flow to DP #1."

pages requested - 21 thru 31 + drawing + map.