

The McKownville Improvement Association

McKOWNVILLE
ALBANY 3, NEW YORK

March 21, 1975

Mr. Durwood Brewer, Superintendent
Department of Water and Sanitation
Guilderland Town Hall
Guilderland, New York 12084

Dear Mr. Brewer:

It appears that vandals have damaged the Bilco-type vault doors on the valve pit located southeast of the McKownville Reservoir spillway and east of the filtration plant.

I hope that repairs can be made promptly in order to avoid more serious vandalism of the vault's interior.

Very truly yours,

John K. Esler
President

JKE:at

cc: Mr. Carl Walters
Mr. Fred Abele